



2009235

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. UTR 000 000 661		Manifest Document No. 040601		2. Page 1 of 1							
3. Generator's Name and Mailing Address US EPA REGION 8 999 18TH ST. SUITE 300 DENVER, CO, 80202-2466													
4. Generator's Phone (303) 312-6983													
5. Transporter 1 Company Name MP ENVIRONMENTAL		6. US EPA ID Number CAT 000 624 247		A. State Transporter's ID N/A									
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone 877-800-5111									
				C. State Transporter's ID									
				D. Transporter 2 Phone									
9. Designated Facility Name and Site Address CLEAN HARBORS GRASSY MOUNTAIN FACILITY 3 MILES EAST 7 MILES NORTH OF EXIT 41 OFF IBO		10. US EPA ID Number UTD 991 301 748		E. State Facility's ID									
				F. Facility's Phone 801 323-8900									
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity							
				No. Type		Unit Wt./Vol.							
a. 'RQ' ASBESTOS, 9, NA 2212, PG III				002 CM		00040 CY							
b.													
c.													
d.													
G. Additional Descriptions for Materials Listed Above 11A) CH 65634B 2 x 25 YD ROLLOFF (ASBESTOS CONTAMINATED PPE + DEBRIS - DOUBLE BAGGED) + WETTED SALES ORDER # D9793803				H. Handling Codes <table border="1"> <tr> <td>CR</td> <td>States Listed Above</td> </tr> <tr> <td>FS</td> <td>AM</td> </tr> <tr> <td>OFFC</td> <td></td> </tr> </table>				CR	States Listed Above	FS	AM	OFFC	
CR	States Listed Above												
FS	AM												
OFFC													
15. Special Handling Instructions and Additional Information USE STANDARD PROTECTIVE CLOTHING EQUIPMENT + CLOTHING. BOX # 522263154 EMERGENCY # (888) 814 7477 24 HR.													
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.													
Printed/Typed Name CRAIG MYERS For FLOYD NICHOLS				Signature <i>Craig Myers</i>		Date 6/1/04							
17. Transporter 1 Acknowledgement of Receipt of Materials				Date									
Printed/Typed Name GARY HILL				Signature <i>Gary Hill</i>		Date 6/1/04							
18. Transporter 2 Acknowledgement of Receipt of Materials				Date									
Printed/Typed Name				Signature		Date							
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.													
Printed/Typed Name Ashley Maestas				Signature <i>Ashley Maestas</i>		Date 6/1/04							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



LOAD SUMMARY RECORD

GM 4561

7:23 AM 06 02 04
44740 1b

LOAD DISPOSAL DESTINATION					
<input type="checkbox"/> STABILIZATION	<input checked="" type="checkbox"/> RCRA CELL 7	<input type="checkbox"/> TSCA CELL	<input type="checkbox"/> SPOT STABILIZATION		
LOAD TRACKING INFORMATION					
PLANT RECEIVED	DROPPED	FINAL CODE	REVIEWED	WEIGHTS	GRIDS
		22P		33M AM	AM AM
DATE		LOAD NO.			
6/2/04		20040022.00			
GENERATOR			HAULER		
US EPA			MP		
ORDER NO.			DRUM NO.		
D9T193803			5352833 / 5352834		
TRUCK NO.		CONTAINER NO. (s) / RAILCAR NO.			
571		52226 / 3154			
CONTAINER TYPE:			LOAD COUNT (RAIL ONLY):		
ED <input checked="" type="radio"/> TT FB V OTHER			1 2 3 4		
OPERATOR SIGNATURE			COUNT		DATE

10:03 06 02 04
44740 1b (H)
41480 1b TARE
3260 1b NET

LOAD WASHOUT INFORMATION		WASHOUT STAMP
WASHOUT:	TYPE:	
YES NO	INTERIOR EXTERIOR	
WASHOUT SIGNATURE	DATE	
DRIVER SIGNATURE	DATE	

ITEM	COMMENTS	NAME	DATE

Clean Harbors Grassy Mountain Facility, Tooele County, Utah

WHITE - Facility

CANARY - Generator

PINK - Transporter

GREEN - Receiving

GOLD - Operations